



1975 Swearingin Fairchild SA-226T Merlin III A

TSN: 6,100 hours
Left Engine: 3,926.3 (5400 TBO)
Right Engine: 3,919.9 (5400 TBO)
TS HSI: 0

Both Left and Right Propellers will be 0 TSO with brand new blades!
Fresh ABCD Inspection

AVIONICS

VHF 20 COMMS (With dual heads)	Collins VIR 30 NAVS
RDR 1200 Radar Linked to EX-500 for Color	Collins Altitude Alerter
Garmin 400 (IFR Certification) GPS	EX500 Avidyne Flight Max
Garmin 150 GPS	Collins AP 105 Auto
PilotDual RMI's	Collins HSI
P5 Engineering PM-1000 Intercomm	Avidyne EX 500 MFD
Air Cycle Machine, 1 Old Style, 1 New Style	Collins ADF
Collins TDR-90 Transponder	

ADDITIONAL FEATURES

Good Glass	Strobes
Fresh Static and Altimeter Check	Clean Panel
13" Monitor	DVD Entertainment 10 Disc

INTERIOR

Tan Leather Seats, New Side Panels and Carpet, Very Nice, Rated 8.

EXTERIOR

4/12/2010 Left for Paint Shop, Midland, TX... You can still pick colors!

This aircraft had a Nose Gear Collapse in Chicago 10 – 12 months ago.
Engines are not the same that were on aircraft during Nose Gear Collapse.